



1/17

Fig. 1



0078392-05204

2/17



3/17





Fig. 1b

4/17


Fig. 2



105290:26282/60

5/17

Fig. 2a



0978392-063604

6/17
Fig. 3a




Fig. 3b




Fig. 3c




Fig. 3d





Fig. 3e



09778392-062504

7/17

Fig. 4a




Fig. 4b






Fig. 4c





8/17

Fig. 5b




Fig. 5a




FIG. 5a

Fig. 6a




Fig. 6b






Fig. 6c



10/17

Fig. 7



FOSS290-2628460

Fig. 8A




Fig. 8B




Fig. 8C




Fig. 10A 12/17




Fig. 9A




Fig. 10B




Fig. 9B




Fig. 10C




Fig. 11




Fig. 12




Fig. 13A





Fig. 13B



15/17

Fig. 14A






Fig. 14B



105290-262260

Fig. 15



10978390-26E8260

Fig. 16A




Fig. 16B




Fig. 16C

